

RYOBI 3200E

Frequently Used Part Numbers

Rollers

X07-0106	Form Roller, Soft
X07-0352	Pan Roller, Soft
X07-0403	Oscillator Roller, Hard
XSA-070243	Metering Roller Assy., Hard (Roller, shaft, bearings, sleeves)

Side Frame Assemblies

XSA-010328O	OPS Side Frame Assy. (Side frame w/ bearings)
XSA-010328N	NOPS Side Frame Assy. (Side frame w/ bearings)

Hanger Bracket Kit

XSA-STDHANGERS	OPS & NOPS Hanger Assy. (Kit does both hangers)
----------------	--

Gears

XSA-03211526	Pan Gear Assy. (Gear w/ clutch bearing)
XSA-03211538	Form Gear Assy. (Gear w/ clutch bearing)
XSA-03211520	Idler Gear Assy. (Gear w/bushing, bolt)

Side Frame Bearings

X06-108	Sealed Ball Bearing (Requires qty. 4)
---------	--

Miscellaneous


XSA-9903	Metering Thumb Screw Assy. (Thumb screw, ratchet gear, set screw)
X09-0201	Compression Spring
XSA-1103	Water Pan Assy. (w/ bottle bracket & pan bolts)
X99-28	Water Pan Hose
XSA-9905	Water Bottle (w/ cap)
X99-61	Wash Up Bottle
X88-30	Installation Manual

PRINTERS PARTS

800-543-1117 201-935-9595

fax 800-392-4072 201-935-5333

www.ppsnj.com



Adjustments

- a. Metering to Pan
- b. Form to Plate

Roller Description

P	=	Pan, Soft
M	=	Metering, Hard
O	=	Oscillator, Hard
F	=	Form, Soft